Property Assessed :	
1X Quarry Green	
1X Quarry Green, Kirkby	
Merseyside	
High Rise	
L33 8XY	
Property Reference :	
Property Reference : 004150	
004150	Reassessment Date :
Property Reference : 004150 Date of Inspection : 20/03/2025	Reassessment Date : 20/03/2026
004150 Date of Inspection : 20/03/2025	
004150 Date of Inspection :	





EXECUTIVE SUMMARY

Responsible Person:	Livv Housing Group
Property Designation	General Needs
Management Extent	Partially Managed Building - Manager or Senior Staff not onsite regularly
No of Floors	16
No of Flats (if applicable)	60
Ground floor Area (m2)	731
Total Area of all Floors (m2)	11696
FRA Completed By	Lee Coyne
QA Carried Out By	Kevin Hudson

U (Urgent)	U	0
A (High)	A	0
B (Medium)	В	3
C (Low)	С	0
R (Recommendation)	R	1
Man 1 (Urgent Management Action)	Man1	0
Man 2 (Management Action)	Man2	0
Total:	4	

Recommended evacuation strategy:	Stay-put
Assessment Risk Rating:	Medium
On satisfactory completion of all remedial works the risk rating of this building may be reduced to:	

Limitation of Report

This fire risk assessment report represents the Fire Risk Assessment Company's understanding for the current building designs and use, the fire strategy and proposed evacuation procedures. It is to provide an assessment of the risk to life from fire and does not address building or property protection or business continuity. The report is not an assurance against risk and is based on the best judgement of the consultant involved. The assessment may rely on information given by others and no liability is accepted for the accuracy of such information. Should any of the buildings (or their operations) change in any way the risk assessment should be updated accordingly. In addition, it is recommended that this fire risk assessment is reviewed at least annually. Each fire risk assessment identifies areas to which access was not available during the inspection. In certain instances we may have made recommendations for further inspection in the report, however as a general guidance we would recommend that the 'no access' areas are inspected as soon as possible.



Action Plan

Question Number	Category	Priority	Comments	Recommendation	Quantity	To Be Completed By
J1	J - Other Significant Hazards	В	Bag present to riser cupboard at first floor level.	Remove.	1	20/03/2026
L2	L - Flat Entrance Doors	В	 Multiple issues identified including. Flat 56 - excessive door gaps between door leaf and frame which exceed recomended tolerances. Flat 56 - damaged smoke seals. Flat 52 - excessive door gaps between door leaf and frame which exceed recomended tolerances. Flat 52 - excessive door gaps between door leaf and frame which exceed recomended tolerances. Flat 52 - damaged smoke seals. Flat 52 - door doesn't fully self-close and becomes caught on latch. Flat 47 - damaged smoke seals. Flat 47 - excessive door gaps between door leaf and frame which exceed recomended tolerances. Flat 47 - loose wiring present above flat entrance door which requires tying back. Flat 45 - large vertical crack noted to door. Flat 45 - damaged smoke seals. Flat 42 - damaged smoke seals. Flat 42 - door slams shut. 	Overhaul / repair all doors as per the above with the exception to flat 45 entrance door. Flat 45 entrance door will require replacing with new FD30S unit complete with head self-door closer.	1	20/03/2026



M1	M - Common Area Fire Doors	В	Cracked glazing to front ground floor communal door.	Repair.	1	20/03/2026
Q10	Q - Limiting Fire Spread	R	Unknown surface spread of flame rating.	Confirm paint specification or alternatively undertake flake sample testing to determine paint build up and suitability prior to next cyclical decorations.	1	Unlimited



Desktop Risk Profile for Premises	Medium
Property Classification	Level 1
Responsible Person	The Responsible Person is the Livv Housing Group.
BAFE SP205 Certificate Number	Refer to Master Property List

General Information

Property Reference	004150
Name	1X Quarry Green
Address 1	1X Quarry Green
Address 2	Kirkby
Address 3	Merseyside
Address 4	High Rise
Postcode	L33 8XY
Fire Risk Assessor	Lee Coyne
Date of inspection	20/03/2025
Checked by:	Kevin Hudson
Recommended reassessment date (subject to appropriate interim management)	20/03/2026

The Premises

Property Designation	General Needs
Property Type	High Rise (6 storeys +)
Number of Floors	16
No of Flats (if applicable)	60
Approx Ground Floor Area (M2)	731
Total Area Of All Floors Area (M2)	11696
Building Description	16 storey tower block comprising of 60 flats. Building is of concrete frame construction with a single stairwell. There are 2 no. passenger lifts.
Building Constructions	1960's construction consisting of perimeter brickwork walls, concrete frame and concrete floors. Exposed perimeter ring beam is noted to each floor level.
Extent Of Common Areas	Circulation spaces.
Areas of the building to which access was not available	Multiple flats and multiple risers
If applicable, state which flats were sample inspected	56, 52, 47, 45, 42 & 43



The Occupants

Management Extent	Partially Managed Building - Manager or Senior Staff not onsite regularly
Details of any onsite management	On site caretaker staff during working hours
Person managing fire safety in premises	LIVV housing group
Person consulted during the fire risk assessment	None
Number of occupants	<125
Number of employees	1
Number of members of the public	<65
Identify any people who are especially at risk	Sleeping occupants, Occupants in remote areas and lone workers

Other Information

Fire Loss experience (since last FRA)	No
Other Comments	No previous fire loss known for this property, no records provided or seen
Any other relevant information	C365 check undertaken on 25.03.25. NSI certificate number 449135. The life safety elements of this fire risk assessment comply with BAFE SP205 scheme which insures that we and our risk assessment staff have met the required technical and quality management standards. Ridge & Partners LLP (BAFE NSI00497) certify requirements in the BAFE SP205 scheme and respect of life safety fire risk assessment and have been complied with. Any questions can be addressed to the assessor or the quality manager. Assessors draw on a variety of methodologies (including PAS 79) guidance and statutory legislation. In this assessment the assessor has paid specific attention to: Regulatory Reform Fire Safety Order 2005 and Fire safety in purpose built blocks of flats.

Fire Safety Legislation

The following fire safety legislation applies to these premise	Regulatory Reform (Fire Safety) Order 2005
What guidance was used for this assessment	Fire Safety in Purpose Built Flats

A - Electrical Ignition Sources

			Response	Quantity	Priority
A1	Was access gained to the electrical intake/meter cupboard for the block?	Yes			
	Comments		Access gained to electrical intake cupboard.		
A2	Is fixed installation periodically inspected and tested?	Yes			
	Date of last fixed electrical installation inspection		2022-04-25		
	Comments		Periodic inspections of the fixed electrical system are undertaken with records held system.		
A3	Is the common area fixed installation free from visible defects?	Yes		-	
	Comments				
A4	Is PAT testing in common areas carried out (annually)?	Not Applicable		-	
	Comments		No portable appliances to common areas.		
A5	Is there a policy for personal electrical appliances?	Not Applicable		- -	
	Comments				
A6	Is the use of adapters and leads limited?	Not Applicable		-	
	Comments		No leads or adaptors to common areas.		



			Response	Quantity	Priority
B1	Are there suitable arrangements for those who wish to smoke? (state what the arrangements are)	Yes			
	Comments				
B2	Is there a policy in place to prevent or restrict smoking within the building?	Yes			
	Comments		Permitted to resident flats.		
В3	Does the policy in relation to smoking appear to be observed?	Yes			
	Comments				
B4	Is there adequate provision of 'No Smoking' signage within the common area?	Yes			
	Comments				

housing group

C - Arson

			Response	Quantity	Priority
C1	Are premises secure against arson by outsiders? (Please state how)	Yes			
	Comments		Perimeter of property is secure.		
C2	Are bins secured / stored in a suitable location? (Please state bin type, location, if and how it is secured)	Yes			
	Comments		External bin store noted.		
C3	Are bins secured within the designated storage location? (Please state how bins are secured)	Yes			
	Comments				
C4	Is fire load close to the premises minimised?	Yes			
	Comments				

D - Space Heating

e opace	induting				
			Response	Quantity	Priority
D1	Are the common areas of the building provided with any form of FIXED space heating system? (State type provided)	Not Applicable			
	Comments				
D2	Are fixed heating systems maintained (annually)?	Not Applicable			
	Date of last Fixed Heating System Inspection				
	Comments				
D3	Are the common areas of the building provided with any form of PORTABLE space heating system? (State type provided)	Not Applicable		-	
	Comments				
D4	If used, is the use of portable heaters regarded as safe?	Not Applicable		-	
	Comments				

E - Cooking

			Response	Quantity	Priority
E1	Are common cooking facilities provided in the block?	Not Applicable			
	Comments				
E2	Are reasonable measures in place to prevent fires as a result of cooking?	Not Applicable			
	Comments				
E3	Are filters changed and ductwork cleaned?	Not Applicable			
	Comments				
E4	Are suitable extinguishing appliances available?	Yes			
	Comments		Present to caretaker areas only.		
E5	Is the provision of fire blankets within the common kitchen considered adequate?	Not Applicable			
	Comments				



F - Lightning


		Response	Quantity	Priority
F1 Does the building have a lightning protect system?	tion Yes			
	Comments			
F2 Is it considered unnecessary to have a sp system is required?	ection Yes			
	Comments			
F3 Does the lightning protection system app in good visual condition?	ear to be Yes			
	Comments			

G - House-Keeping

			Response	Quantity	Priority
G1	Is the property regularly cleaned to prevent the build up of combustibles?	Yes			
	Comments				
G2	Combustible materials not kept near sources of ignition?	Yes			
	Comments				
G3	Escape routes kept clear of items combustible materials or waste?	Yes			
	Comments				
G4	Escape routes kept clear of any trip hazards?	Yes			
	Comments				
G5	Any hazardous materials are stored correctly?	Yes			
	Comments		Designated cupboard noted to caretaker area.		
G6	Are all other house-keeping issues satisfactory?	Yes			
	Comments				



H - Contractors




I - Dangerous Substances

			Response	Quantity	Priority
11	If dangerous substances are used, has a risk assessment been carried out as required by the Dangerous Substances and Explosives Atmospheres Regulations 2002?	Not Applicable			
	Comments				
12	Has a risk assessment been carried out as required by the Dangerous Substances & Explosives Atmosphere Regulations 2002?	Not Applicable			
	Comments				







K - Means of Escape

			Response	Quantity	Priority
К1	Is escape route design deemed satisfactory?	Yes			
	Comments				
K2	Are the escape routes adequately protected? (Consider lobby protection to staircase, if needed)	Yes			
	Comments				
К3	Is there adequate provision of exits, for the numbers who may be present?	Yes			
	Comments		Two principal final exits to ground floor.		
К4	Is there adequate exit width, for the numbers who may be present?	Yes			
	Comments				
К5	Are doors on escape routes easily opened? (and are sliding or revolving doors avoided?)	Yes			
	Comments		Push buttons to final exits.		
K6	Are doors or gates on escape routes provided with electrically operated access control systems? (Describe provision)	Yes			
	Comments				





			Response	Quantity	Priority
К7	Are electrically operated access control systems fitted to doors or gates on escape routes provided with over ride facilities and/or designed to 'fail safe' on power failure?	Yes		_	
	Comments		Maglocks systems are understood to have a fail safe device, however there is also a green break glass manual override to the internal face of exits.		
K8	Do final exits open in the direction of escape where necessary?	Yes			
	Comments				
K9	Are travels distances satisfactory? (consider single direction and more than one direction)	Yes		-	
	Comments				
K1	Are there suitable precautions for all inner rooms?	Not Applicable		1	
	Comments				
K1 ⁻	Are escape routes separated where appropriate?	Yes]	
	Comments				
K1:	2 Are corridors sub-divided where appropriate?	Yes		-	
	Comments				
K1:	3 Do escape routes lead to a place of safety?	Yes		1	
	Comments				
K14	Are the stairs and/or lobbies provided with adequate ventilation? (If considered satisfactory, please state provision)	Yes			
	Comments		A combination of AOV's and manually operable windows to stairwells, along with open ventilation to historic rear bin store areas which are now locked and remain redundant.		
K1	Are the stairs and/or lobbies provided with an adequate automatic or remotely operated smoke ventilation system? (State provision)	Yes			
	Comments		As above.		
K10	Are there suitable arrangements in the building for means of escape for disabled persons?	Not Applicable			
	Comments				
K1	Are all other means of escape issues satisfactory? [1]	Yes		a	
	Comments]	



			Response	Quantity	Priority
K18 Are all othe [2]	er means of escape issues satisfactory?	Yes			
	Comments				
K19 What is the building?	e current evacuation strategy for the	Stay-put			
	Comments				
K20 Is the curre considered	ent evacuation strategy for the building	Yes			
	Comments				
K21 Recomment building is:	nded evacuation strategy for this	Stay-put			
	Comments				

L - Flat Entrance Doors

			Response	Quantity	Priority
L1	Are flat entrance doors or doors / frames appropriately fire rated?	Not Known			
	Comments		Only a sample inspection was undertaken to flat 56, 52, 47, 45, 42 & 43.		
			However it is our understanding that routine fire door inspections are carried out LIVV housing group across all of there associated fire doors under a separate inspection programme.		

			Response	Quantity	Priority
L2	Are fire rated flat entrance doors in good condition - not in need of repair?	No			
			Multiple issues identified including.		
	F		Flat 56 - excessive door gaps between door leaf and frame which exceed recomended tolerances.		
			Flat 56 - damaged smoke seals.		
	F		Flat 52 - excessive door gaps between door leaf and frame which exceed recomended tolerances.		
			Flat 52 - damaged smoke seals.		
			Flat 52 - door doesn't fully self-close and becomes caught on latch.		
	Comments		Flat 47 - damaged smoke seals.		
			Flat 47 - excessive door gaps between door leaf and frame which exceed recomended tolerances.		
			Flat 47 - loose wiring present above flat entrance door which requires tying back.		
			Flat 45 - large vertical crack noted to door.		
			Flat 45 - damaged smoke seals.		
			Flat 42 - damaged smoke seals.		
			Flat 42 - door slams shut.		
			Overhaul / repair all doors as per the above with the exception to flat 45 entrance door.		
	Recommendation		Flat 45 entrance door will require replacing with new FD30S unit complete with head self-door closer.		В
L3	Is all glazing to flat entrance doors appropriately fire rated?	Not Applicable			
	Comments				
L4	Are fan lights above flat entrance doors appropriately fire rated?	Yes			
	Comments				
L5	Are side panels to flat entrance doors appropriately fire rated?	Not Applicable			
	Comments				
L6	Are flat entrance doors fitted with adequate self- closing devices? (From sample inspection)	Yes			
	Comments		Noted to all sample inspected flats.		

housing group



			Response	Quantity	Priority
L7	Are flat entrance doors fitted with intumescent strips and cold smoke seals? (From sample inspection)	Yes			
	Comments		Noted to all sample inspected flats.		
L8	Are letterboxes satisfactory? (State only if missing, damaged or uPVC)	Not Known			
	Comments				
L9	Are all other flat entrance door issues satisfactory? [1]	Not Known			
	Comments				
L10	Are all other flat entrance door issues satisfactory? [2]	Not Known			
	Comments				

M - Common Area Fire Doors

			Response	Quantity	Priority
M1	Are all common area fire doors and/or frames appropriately fire rated?	No			
	Comments		Cracked glazing to front ground floor communal door.		
	Recommendation		Repair.	1	В
M2	Are all common area fire rated fire doors in good condition - and not in need of repair?	Yes			
	Comments				
М3	Is all glazing to common area fire doors appropriately fire rated?	Yes			
	Comments				
M4	Are fan lights/side panels to common area fire doors appropriately fire rated?	Not Applicable			
	Comments				
M5	Are self-closing devices on common area fire doors adequate? (Where appropriate)	Yes			
	Comments				
M6	Are intumescent strips and smoke seals provided to common area fire doors?	Yes			
	Comments				
M7	Are common area fire doors adequate otherwise? (Ironmongery, hold open hooks etc.)	Not Applicable			
	Comments				
M8	Are all other fire door issues satisfactory?	Yes			
	Comments				



N - Emergency Lighting

			Response	Quantity	Priority
N1	Is emergency lighting provided to the common areas of the block? (If yes then describe provision)	Yes			
	Comments				
N2	If emergency lighting is provided, is it in good working order?	Yes			
	Comments				
N3	If emergency lighting is provided, is coverage sufficient? (Internal and external)	Yes			
	Comments				
N4	If EL not provided, is borrowed/artificial lighting sufficient for escape? (Internal and external)	Not Applicable			
	Comments				

O - Fire Safety Signs and Notices

			Response	Quantity	Priority
01	Is there adequate provision of fire safety signs and notices? (Consider directional, exits, stairs, fire action notices, fire equipment and 'do not use lift' signage)	Yes			
	Comments		Fire action and electronic notice boards present to internal communal area.		
02	Is fire door signage adequate? (Consider 'Fire door keep shut' and 'Fire door keep locked shut' signage)	Yes			
	Comments				
O3	If required, is directional/exit signage adequate?	Yes			
	Comments				
04	Are other fire safety signs adequate and clearly visible?	Yes			
	Comments				
05	Are other fire safety signs issues satisfactory?	Yes			
	Comments				



			Response	Quantity	Priority
P1	Has the building got a manually operated electrical fire alarm system?	Yes			
	Comments		Grade A fire alarm noted to entrance lobby area. There are also repeater panels present to caretaker areas within the building. It is also our understanding that there is a fire alarm control panel which is present within block 2 (the main caretaker office area) whereby caretaker staff can manage fire alarm during working hours from their office which is interlinked with all 3 no. blocks on site.		
P2	If common area AFD and/or alarm system is installed, is it in good working order?	Yes			
	Comments		L3 & L5 coverage to common / caretaker areas.		
P3	If installed, is the common area AFD adequate for the occupancy and fire risk?	Yes			
	Comments				
P4	If not installed, are the premises deemed safe without a common area AFD system?	Yes			
	Comments				
P5	If applicable, is separate domestic hard-wired smoke/heat alarm within the flats installed to a suitable standard?	Yes			
	Comments		During sample inspection of flat 56 & 45 it was noted that a Grade D LD1 fire alarm was in operation. All remaining flats are understood to provide a minimum Grade D LD2 coverage which includes those which were sample inspected.		
P6	Is a social alarm system required to allow remote monitoring of independent domestic hard-wired smoke/heat alarm systems within the flats? (Sheltered accommodation)	Yes			
	Comments				
P7	Is the building provided with a remotely monitored social alarm system? (Sheltered accommodation)	Yes			
	Comments				
P8	Are independent domestic hard-wired smoke/heat alarm systems within the flats adequately monitored via a social alarm system? (Sheltered accommodation)	Yes			
	Comments				
P9	Are all other AFD and alarm system issues satisfactory?	Yes			
	Comments				

Livv


housing group



			Response	Quantity	Priority
P10	Are all other fire detection and alarm system issues satisfactory? [1]	Yes			
	Comments				
P11	Are all other fire detection and alarm system issues satisfactory? [2]	Yes			
Comments					

Q - Limiting Fire Spread

			Response	Quantity	Priority
Q1 (Is the level of compartmentation adequate? (Special consideration should be given to converted or non 'purpose built' premises)	Yes			
	Comments		It is anticipated that 60 minutes fire resistance is provided subject to addressing actions within this report.		
	Are hidden voids appropriately enclosed and/or fire-stopped? (consider above suspended ceilings)	Not Applicable			
	Comments				
Q3 0	Are risers (shafts, ducts and cupboards) in the common area appropriately enclosed and/or fire-stopped?	Yes			
	Comments		Notable fire stopping present across building including to electrical cupboard.		
Q4 a	Are pipes and other services provided with adequate fire-stopping measures as required where they pass through fire resisting construction? (Consider fire collars etc)	Not Applicable			
	Comments				
Q5 a	If a waste chute is provided within the building are adequate measures in place to limit fire spread/growth? (Consider dampers etc)	Not Applicable			
	Comments				
Q6 I	Is compartmentation maintained in the roof space?	Not Applicable			
	Comments		No roof space.		
07	Are electrics enclosed in fire rated construction? (Where necessary)	Yes			
	Comments				
Q8 I	Is compartmentation maintained at electrical meter	Not Applicable			
	Comments				



housing group



	Response	Quantity	Priority
Comments			


R - Fire Extinguishing Appliances

			Response	Quantity	Priority
R1	If required, is there reasonable provision of portable fire extinguishers?	Yes			
	Comments				
R2	Is the provision of portable fire extinguishers considered appropriate given the building occupancy?	Yes			
	Comments				
R3	Is the provision of portable fire extinguishers considered adequate for the building?	Yes			
	Comments				
R4	Are all fire extinguishing appliances readily accessible?	Yes			
	Comments				
R5	Are portable fire extinguishers required in the common areas?	Not Applicable			
	Comments				



			Response	Quantity	Priority
S1	Is the building provided with drop key override switch facilities for Fire and Rescue Service access?	Yes			
	Comments		Fire service drop key and Gerda box noted to main entrance for the attention of fire service.		
S2	Is the building provided with a fire mains system? (Dry or wet riser etc.)	Yes			
	Comments		Fire stopping noted to riser cupboards.		
S3	Is the building provided with a lift (or lifts) used for fire safety purposes? (Firefighting, fireman's or evacuation lift)	Yes			
	Comments				
S4	Is the building provided with disabled evacuation aids? (Evacuation chairs, sheets, mats or sledges etc.)	Not Applicable			
	Comments				
S5	Is a sprinkler system provided within the building? (provide details of type and extent)	Not Applicable			
	Comments				
S6	Are hose reels provided within the building?	Not Applicable			
	Comments				
S7	Is any other relevant system/equipment installed? [1] (state type of system and comment as necessary)	Yes			
	Comments		Evacuation alarm monthly inspection compliant until 10.04.25. 6 month testing compliant 17.08.25. 12 month full load test compliant until 17.02.26.		
S8	Is any other relevant system/equipment installed? [2] (state type of system and comment as necessary)	Not Applicable			
	Comments				
S9	Is any other relevant system/equipment installed? [3] (state type of system and comment as necessary)	Not Applicable			
	Comments				





housing group



			Response	Quantity	Priority
T12	Are all other fire safety management issues satisfactory?	Yes			
	Comments				
U - Training	and Drills				
			Response	Quantity	Priority
U1	Do staff receive adequate induction and annual refresher fire safety training? To include fire risks in the premises, fire safety measures in the building, action in the event of fire and on hearing alarm, location and use of fire extinguishers.	Yes			

	location and use of fire extinguishers, calling the fire service.		
	Comments		
U2	Are employees nominated to assist in the event of fire given additional training?	Not Applicable	
	Comments		
U3	Are staff nominated and trained on the use of fire extinguishing appliances?	Yes	
	Comments		
U4	Are fire drills carried out at appropriate intervals?	Not Applicable	
	Comments		

V - Testing and Maintenance

		Response	Quantity	Priority
V1 Is the fire alarm system tested weekly and periodically serviced?	Yes			
Comments		Weekly testing compliant until 25.03.25. 6 month servicing compliant until 24.04.25.		
V2 Is the emergency lighting system tested monthly and annually?	Yes		_	
Comments		Monthly testing compliant until 10.04.25. Annual servicing compliant until 22.05.25.		
V3 Are fire extinguishers serviced annually?	Yes			
Comments		Monthly inspection compliant until 10.04.25. Annual servicing compliant until 01.05.25.		

			Response	Quantity	Priority
V4	Are rising mains inspected six-monthly and tested annually?	Yes			
	Comments		Annual service compliant until 25.10.25.		
V5	Is the lightning protection system annually inspected and tested?	Yes			
	Comments		Compliant until 13.11.25.		
V6	Are fire blankets tested and serviced in accordance with relevant guidance?	Not Applicable		•	
	Comments				
V7	Is the smoke control system inspected, tested and serviced in accordance with relevant guidance?	Yes		-	
	Comments		AOV 6 month servicing compliant until 13.09.25. Monthly testing compliant until 10.04.25.		
V8	Are access control systems inspected, tested and serviced in accordance with relevant guidance?	Yes			
	Comments		Compliant until 07.01.26.		
V9	Are drop key override switch facilities for Fire and Rescue Service access inspected, tested and serviced in accordance with relevant guidance?	Not Applicable			
	Comments				
V10	Are lifts in the building used for fire safety purposes inspected, tested and serviced in accordance with relevant guidance? (Firefighting, fireman's or evacuation lift)	Not Applicable			
	Comments				
V11	Is the sprinkler system provided within the building inspected, tested and serviced in accordance with relevant guidance?	Not Applicable		I	
	Comments				
V12	Are hose reels provided within the building inspected, tested and serviced in accordance with relevant guidance?	Not Applicable			
	Comments				
V13	Are the disabled evacuation aids regularly inspected, tested and serviced?	Not Applicable		-	
	Comments				
V14	Are all other systems serviced? (Consider fire- fighting lifts, sprinkler systems)	Not Applicable			
	Comments				

Livv

housing group



			Response	Quantity	Priority
V15	Is the fire safety system or equipment detailed in S8 inspected, tested and serviced in accordance with relevant guidance? [1]	Yes			
	Comments				
V16	Is the fire safety system or equipment detailed in S9 inspected, tested and serviced in accordance with relevant guidance? [2]	Yes			
	Comments				

W - Records

			Response	Quantity	Priority
W1	Is there a log book on the premises?	Not Applicable			
	Comments		Present on C365.		
W2	Are fire drills recorded?	Not Applicable			
	Comments				
W3	Is fire training recorded?	Yes			
	Comments				
W4	Are routine in-house fire safety checks recorded?	Yes			
	Comments				
W5	Are fire alarm tests recorded?	Yes			
	Comments				
W6	Are emergency lighting tests recorded?	Yes			
	Comments				
W7	Are records kept of the fire extinguisher inspections, tests and servicing?	Yes			
	Comments				
W8	Are fire mains inspections, tests and services recorded?	Not Applicable			
	Comments				
W9	Are records kept of the lightning protection system inspections, tests and servicing?	Yes			
	Comments				



			Response	Quantity	Priority
W10	Are fire blanket inspections and servicing recorded?	Not Applicable			
	Comments				
W11	Are the smoke control system inspections, test and servicing recorded?	Yes			
	Comments				
W12	Are the access control systems inspections, test and servicing recorded?	Yes			
	Comments				
W13	Are drop key override switch facilities inspections, tests, and services recorded?	Not Applicable			
	Comments				
W14	Are lifts inspections, tests and services recorded?	Not Applicable			
	Comments				
W15	Are the sprinkler systems inspections, tests and services recorded?	Not Applicable		-	
	Comments				
W16	Are hose reels inspections, tests and services recorded?	Not Applicable			
	Comments				
W17	Are the disabled evacuation aids inspections, tests and services recorded?	Not Applicable			
	Comments				
W18	Is testing/maintenance of any other fire protection systems recorded?	Not Applicable		_	
	Comments				
W19	Are records kept of the inspections, tests or services for other relevant system/equipment noted [1]?	Not Applicable			
	Comments				
W20	Are records kept of the inspections, tests or services for other relevant system/equipment noted [2]?	Not Applicable			
	Comments				

Livv

housing group



X - Electrical Services				
		Response	Quantity	Priority
Are any wiring systems visible within the common escape route(s) supported in accordance with BS 7671:2011 (as amended) such that they will not be liable to premature collapse in the event of fire? (Consider the use of non-metallic cable clips, cable ties)	Not Applicable			
Comments				

Y - Gas Services

			Response	Quantity	Priority
¥1	Are there any fixed gas installations present within the common parts of the building? (Consider gas pipework and meters)	Not Applicable			
	Comments				
Y2	Are the fixed gas installations within the common areas adequately enclosed in fire resisting construction where required?	Not Applicable		-	
	Comments				
Y3	Is the location and routing of the fixed gas installations within the common areas considered adequate? (Consider proximity to electrical services)	Not Applicable		-	
	Comments				

Z - Other Issues

			Response	Quantity	Priority
Z1	Are all issues deemed satisfactory? [1]	Yes			
	Comments				
Z2	Are all issues deemed satisfactory? [2]	Yes			
	Comments				
Z3	Are all issues deemed satisfactory? [3]	Yes			
	Comments				



Assessment Risk Ratings	
Likelihood of fire	Medium
Potential consequences of Fire	Moderate Harm
Premises Risk Rating	Medium
On satisfactory completion of all remedial works the risk rating of this building may be reduced to	Moderate



RISK RATING

The following simple risk level estimator is based on a more general health and safety risk level estimator of the type contained in BS 8800:

	Potential consequences of fire		
Likelihood of fire	Slight harm	Moderate Harm	Extreme Harm
Low	Trivial	Tolerable	Moderate
Medium	Tolerable	Moderate	Substantial
High	Moderate	Substantial	Intolerable

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one advocated by BS 8800 for general health and safety risks:

Risk level	Action and time table
Trivial	No action is required and no detailed records need be kept.
Tolerable	No major additional controls required. However, there might be a need for improvements that involve minor or limited cost
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measuresc
Substantial	Considerable resources might have to be allocated to reduce the risk. If the building is unoccupied, it should not be occupied until the risk has been reduced. If the building is occupied, urgent action should be taken.
Intolerable	Building (or relevant area) should not be occupied until the risk is reduced.

Note that, although the purpose of this section is to place the risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)

FI	RE RISK ASSESSMENT	- INDIVIDUAL RE	COMMENDATION	PRIORITIES AND	TIMESCALES

Taking into account the fireprevention measures observed at the time of this risk assessment, it is	Medium			
considered that the hazard from fire (likelihood of fire) at these Premises is:	modiam			
In this context, a definition of the above terms is as follows: Low: Unusually low likelihood of fire as a result of negligible potential sources of ignition.		Individual Recommendation Priorities:		Recommended Timescales:
Medium: Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).		U (Urgent)	U	1 Day
High: Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.		A (High)	A	3 Months
		B (Medium)	В	12 Months
Taking into account the nature of the building and occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the	Moderate Harm	C (Low)	С	12 Months
consequences for life safety in the event of fire would be:		R (Recommendation)	R	Unlimited
In this context, a definition of the above terms is as follows:		Man 1 (Urgent Management Action)	Man1	1 Month
Slight harm: Outbreak of fire unlikely to result in serious injury or death of any occupant.				
Moderate harmful: Outbreak of fire could foreseeably result in injury (including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.		Man 2 (Management Action)	Man2	3 Months
Extreme harm: Significant potential for serious injury or death of one or more occupants likely to involve multiple fatalities.		Note: The above timescales may be altered refer to the collated action plan	when the action p	plan for this premises is collated with other properties in the stock. Please

Accordingly, it is considered that the risk to life from fire at these premises is:

Moderate


Photographs





A1 - Photo 1

B4 - Photo 2



A2 - Photo 1



B4 - Photo 1







F1 - Photo 1






F1 - Photo 2



G5 - Photo 1



J1 - Photo 1



J2 - Photo 1



J2 - Photo 2



J2 - Photo 3





K3 - Photo 1



K3 - Photo 2



E4 - Photo 1



E4 - Photo 2



E4 - Photo 3



K6 - Photo 1





K7 - Photo 1



K7 - Photo 2



K14 - Photo 1



K14 - Photo 2

K14 - Photo 3



L2 - Photo 1





L2 - Photo 2



L2 - Photo 3



L4 - Photo 1



L6 - Photo 1



L7 - Photo 1



M1 - Photo 1





M1 - Photo 2



M3 - Photo 1



M5 - Photo 1



M6 - Photo 1



M6 - Photo 2



N1 - Photo 1





N1 - Photo 2



O1 - Photo 1



O1 - Photo 2



O2 - Photo 1



O2 - Photo 2



O3 - Photo 1





O3 - Photo 2



P1 - Photo 1



P1 - Photo 2



P5 - Photo 1



P5 - Photo 2









Q3 - Photo 1



Q13 - Photo 1



Q13 - Photo 2



Q13 - Photo 3



S1 - Photo 1



S1 - Photo 2






S2 - Photo 1




S2 - Photo 2



S3 - Photo 1



S7 - Photo 1



S7 - Photo 2




S7 - Photo 3







V1 - Photo 1




V1 - Photo 2




V2 - Photo 1



V2 - Photo 2




V3 - Photo 1




V3 - Photo 2







V5 - Photo 1




V7 - Photo 1



V7 - Photo 2



V8 - Photo 1



V4 - Photo 1

BRITISH APPROVALS FOR FIRE EQUIPMENT

SP205 - Life Safety Fire Risk Assessment

RIDGE



Scheme Registration Certificate

This is to certify that

Ridge and Partners LLP

The Cowyards, Blenheim Park, Woodsotck, OX20 1QR

has satisfactorily complied with the requirements of scheme

BAFE SP205

For Life Safety Fire Risk Assessment

Ridge and Partners LLP is authroised to use the BAFE SP205 mark and can provide on-site services as per scheme requirements.

Kevin Hudson BAFE Accredited Fire Risk Assessment Approver

BAFE SP205 Scheme Registration No: 101710

To check the validity of this certificate please contact the BAFE office (0844 335 0897 / info@bafe.org.uk)

Date of Issue: 26/03/2025

NSI Third Party Certification No: NSI00497

This certification remains the property of BAFE BASFE, The Fire Service College, London Road, Moreton-in-Marsh, Gloucestershire, GL56 0RH

FIRE RISK ASSESSMENT (FRA) ♦ SUMMARY SHEET ♦



Publish Date: 27/05/2025

Property Reference:	004150
Address:	1X Quarry Green
	Kirkby
	Merseyside
	High Rise
	L33 8XY
Date of FRA:	20/03/2025
Target Completion Date for all recommendations:	20/03/2028

Responsible Person:	Livv Housing Group
Property Designation:	General Needs
Management Extent:	Partially Managed Building - Manager or Senior Staff not onsite regularly
No of Floors:	16
No of Flats (if applicable):	60
Ground floor Area (m2):	731
Total Area of all Floors (m2):	11696
FRA Completed by:	Ridge on behalf of Livv Housing Group

PRIORITY KEY

	U (Urgent)	A (High)	B (Medium)	C (Low)	R (Recommendation)	Man 1 (Urgent Management Action)	Man 2 (Management Action)	
--	------------	----------	------------	---------	--------------------	----------------------------------	---------------------------	--

REMEDIAL ACTIONS IDENTIFIED BY FRA

Priority	No. of Actions	Due by Date	Total no. of Actions Completed	Total no. of Actions Outstanding
U	0		0	0
А	0		0	0
В	3	20/03/2026	2	1
С	0		0	0
R	1	20/03/2028	1	0
Man 1	0		0	0
Man 2	0		0	0
Total	4		3	1

Recommended evacuation strategy:	Stay-put
Assessment Risk Rating:	Medium
On satisfactory completion of all remedial works the risk rating of this building may be reduced to:	Moderate